

# STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

# LARGE MINING OPERATIONS 2007 PROGRESS REPORT January 1, 2007 to December 31, 2007

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

	1.	Mine Permit Number: Mo 30025
	2.	Mine Name: LYNN SPRING QUARRY
	3.	Name of Operator/Permittee: WILLIAM L BOWN
		Note: If Operator's address, company representative or phone number have changed, please provide a replacement page to the Notice of Intention.
	4.	Mine Location:
	5.	Report the gross amount of ore mined and waste moved, as well as the arrangement, positioning, or distribution of the material:  FLAGSTONE BLDG. STONE REMOVED 2,412.465 TONS  Gross Ore Mined Tons, or yd3  Waste Material Moved Tons, or 1500 yd3  New Disturbance O Acres during 2007 ALL WORK WITHIN APPROVED DISTURBANCE Area Reclaimed O Acres during 2007  Total Disturbed Area Acres* PLASE REFELTO CURRENT UNDOGM FIGURES ('Ob)  Was the ore shipped off site? If not, where is the ore located? ALL PALLETIZED  STONE WAS SHIPPED OFF- SITE.  Where is the waste located? WASTE IS LOCATED IN PILES ABOUT THE  DISTURBANCE AND STOCKPILED FOR FUTURE USE IN FIRMING PITS, TRAICHES
		*Total life of mine disturbance to the end of 2007.
	6.	Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE for an application for full or partial bond/site release).  THERE WAS NO RECLAMATION PERFORMED IN 107
	7.	Include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
rre		by certify, under penalties of law, the information provided in this report is true and best of my knowledge and belief.
		Name (Typed or Print): WILLIAM L BOWN
		Title of Operator:
		Signature of Operator: Willen & Bou
		Date: 2 15 08
		RECEIVED
form	s\reports\MF	FEB 1 9 2008



# State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

# **Inspection Report** Minerals Regulatory Program

Supervisor

February 14, 2008			
Mine Name: Lynn Springs Quarry Operator Name: Bonneville Quarries, Inc.	Permit number: M/003/0025 Inspection Date: September 13, 2007 Time: 3:00 PM		
<b>Inspector(s):</b> Lynn Kunzler, DOGM			
Other Participants: None			
Mine Status: Active			
<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls,</li> <li>Soils</li> <li>Revegetation</li> </ol>			

### **Purpose of Inspection:**

Routine inspection while in the area.

#### **Inspection Summary:**

There was no activity at this site during this inspection, however, there was equipment on site (excavator) and it appeared that there had been activity within the last day or two. The division had recently received a NOI revision to expand this operation. The FS has indicated that will need to do an EA before they can approve the expansion. They will be close to the first of the year before they will be able to begin the NEPA work.

The access route across FS lands was in good condition, there were no erosion problems noted. The pit has been expanded since the last inspection, but was still within the previously disturbed area footprint. The operator does not have much room left before he will need the expansion area approved. The access road that looped around the pit is no longer accessible to vehicles because of the pit expansion.

The operator has been doing a good job keeping trash picked up. There was, however old equipment on site that did not look operational. If so, the operator should have it removed from the site.

#### **Conclusions and Recommendations:**

Continue to monitor the this operation when in the area.

Inspector's Signature

O:\M003-BoxElder\M0030025-Lynnsprings\inspections\Insp-09262007.doc